


A	816x290x12mm	1PC
1	558x298x12mm	1PC
2	816x290x12mm	1PC
3	756x288x12mm	1PC
4	250x258x12mm	1PC
5	252x42x12mm	2PCS
6	252x42x12mm	1PC
7	516x289x12mm	1PC
8	516x47x12mm	1PC
9	748x247x12mm	1PC
10	764x260x3mm	1PC
11	764x260x3mm	1PC
12	247x176x15mm	4PCS
13	260x115x9mm	4PCS
14	260x115x9mm	4PCS
15	226x115x9mm	4PCS
16	249x234x3mm	4PCS

		15*10mm		6*30mm		←111111111111111111111111111111111111		M3. 5*25mm		~~~~@ M3*12mm		-• M2. 5*14mm			
В	12PCS	С	12PCS	D	28PCS	Е	2PCS	F	32PCS	G	45PCS	Н	2PCS	J	1PC
					9		M4*16mm								
K	1PC	L	2PCS	M	8PCS	N	4PCS	0	1PC	Р	1PC	Q	4PCS	R	1PC
M4*12mm		6*30mm			M4*35mm		M3*14mm								
S	2PCS	T	1PC	U	1PC	V	8PC	W	8PC						


Assembly checklist




Read through the instructions carefully before you begin.



Make sure you have all the required tools. Do not use power tools.



before you begin assembly



Identify and lay out all of the components Do not fully tighten all screws until step/ precess finished.

Useful Information

- ! Never use power tools, they can damage your omponents or hardware if used incorrectly.
- The most common mistakes made during as sembly are using the wrong hardware or getting components back to front.
- Always use a soft surface (such as carpet or cardboard) when assembling your product to avoid scratching or damaging the surface of the product.

